

Trimax Technology – Manufactures of Trimax Meters
www.TrimaxMeters.com


Instructions for Trimax Technology Meter Tool with List Editing capabilities.

All software is offered "as is" and without guarantee. This software is for experienced users only. If you don't have the ability to load this software or if you feel unsure of your abilities, DO NOT use this software. Trimax Meters is in no way responsible for the use or mis-use of this software. Any repairs required because of your use or mis-use of this software will be charged at normal bench repair rates and normal replacement parts cost.


*****USE THIS SOFTWARE AT YOUR OWN RISK*****

Please read and understand these instructions in their entirety before attempting to use this software.

Double click "MeterV1.2.exe" to open the program.




You will see




which means you have connected to the meter.


Click "OK" and you will see the main menu.




Click "Read parameters" to download the meter list from your meter to your PC.



Once downloaded, click "Edit parameters" to edit your file. Choose the file you just saved.




The menu will expand and you will now see the list from your meter.



Notice the buttons "Add SAT", "Delete SAT", "Apply" in the left window, and "Add TP", "Delete TP", "Apply" in the right window. As you add or delete satellites or transponders, click the "Apply" button.

Adding a satellite is easy, just click the "Add SAT" button and you will see



Highlight "Newsatillite" and type in the name you want to use. Tab down to the "degree(0-360)" box and enter the position of the satellite in degrees EAST. If your satellite location is in degrees WEST, simply subtract it from 360 to get degrees EAST.

After adding and/or deleting satellites and transponders, click "Write parameters" to load the file from your PC to your meter.

DO NOT factory reset your meter. [Factory reset will erase your list.](#)

This information provided by:
Trimax Technology
<http://www.TrimaxMeters.com>
sales@trimaxmeters.com